

**From:** Piro, Peter (DPH) <Peter.Piro@MassMail.State.MA.US>  
**Sent:** Tuesday, February 23, 2010 7:56 AM  
**To:** Nassif, Julianne (DPH) <Julianne.Nassif@MassMail.State.MA.US>  
**Cc:** Salemi, Charles (DPH) <Charles.Salemi@MassMail.State.MA.US>  
**Subject:** RE: Painting

---

I gave Room 361 as the main entrance to the lab but we have water leaks in every room.

358-MGL/ZYT/CBS Bad Leaks  
359-GC Instrument Room On occasion but not too bad  
361- DJR/NEM/MAI Bad Leaks and also bad leaks by the break table.  
362-ASD/ELO/DXF Bad Leaks  
363-DCS/LAG/SLF/KAC Very Bad Leaks

Just about all exterior walls leak

---

**From:** Nassif, Julianne (DPH)  
**Sent:** Monday, February 22, 2010 4:44 PM  
**To:** Piro, Peter (DPH)  
**Cc:** Salemi, Charles (DPH)  
**Subject:** RE: Painting

which room is 361? I need to coordinate this w/ John Nickerson

---

**From:** Piro, Peter (DPH)  
**Sent:** Friday, February 19, 2010 9:24 AM  
**To:** Nassif, Julianne (DPH)  
**Cc:** Salemi, Charles (DPH)  
**Subject:** Painting

Dear ppiro,

Your request has been logged as Maintenance Request **#M105664**  
Please, write this number down or print this page for your records and future reference.

Thank you,

The Maintenance Team

PIC# **5301**  
Program **Drug Lab/SLI**

<b>Maintenance Request #M105664</b>
---

Location	<b>Tower</b>	Status	<b>New Request</b>
Room #	<b>361</b>	Requested By	<b>ppiro</b>
Phone	<b>6179836634</b>	Authorized By	
Needed By Date	<b>2/28/2010</b>		
Request Type	<b>Maintenance</b>		

Project Description:

Julie Nassif plans on having the Drug Lab walls painted and possibly the cabinets as well. Please explain to Julie the root cause of the drywall damage to the exterior walls and the solution. In addition, are there any types of drywall that could mitigate damage in problematic applications?